

# COMAC - [www.comac-italy.com](http://www.comac-italy.com)

## DIGIMETERRING

**DIGITAL** meter of the bending radius.

The radius measure is shown directly on the display of the device (no decoding chart).

Range of measured radii: 250 - 700.000mm

Supplied complete with machined bar for zero setting and support for measurement of the inside radius.

Extra support for measurement of the outside radius – optional



Extra support for  
measuring the  
outside radius

